



SERVICE BULLETIN

Classification: BT17-009	Reference: NTB17-074	Date: July 10, 2017
-----------------------------	-------------------------	------------------------

2016-2017 MAXIMA; RUST AROUND REAR LICENSE LAMP FINISHER

APPLIED VEHICLE: 2016-2017 Maxima (A36)

IF YOU CONFIRM

When rust is found on the rear deck lid surface in the area surrounding the license lamp finisher (Figure 1), or when replacing the license lamp finisher for any reason.

ACTION

- Replace the license lamp finisher with the new replacement part listed in **PARTS INFORMATION**.
 - Refer to the Electronic Service Manual (ESM), section **EXT – Exterior**, for removal and installation information.
- Repair any damaged surfaces that were in direct contact with the license lamp finisher.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
FINISHER ASSY-TRUNK LID	84810-4RA3A	1

CLAIMS INFORMATION

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace License Lamp Finisher	(1)	UM30AA	ZA	03	(2)

OR

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace License Lamp Finisher	(1)	UM30AA	ZA	03	(2)
Refinish Trunk Lid-Half Block Repair		ZL1GAA			(3)
Preparation & Mixing Time		ZZ99AA			(3)

- (1) Reference the Parts Information Table and use the applicable Finisher as the PFP.
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.
- (3) Reference the A36 section of the current Nissan Warranty Paint Flat Rate Manual and use indicated FRT.

NOTE: Use expense code 019 for paint materials.

