



SERVICE BULLETIN

Classification:

EC17-017

Reference:

NTB17-090

Date:

August 8, 2017

DTC P0036 DIAGNOSTIC INFORMATION

APPLIED VEHICLES: 2016-2017 370Z Roadster (Z34)
2016-2017 370Z (Z34)
2016-2017 Altima w/V6 engine (L33)
2017 Armada (Y62)
2016-2017 Murano (Z52)
2016-2017 Pathfinder w/V6 engine (R52)

SERVICE INFORMATION

The Electronic Service Manual (ESM) information for DTC P0036 may be inaccurate or incomplete for the Applied Vehicles.

If an Applied Vehicle stores a DTC P0036, follow diagnostic procedures in the ESM for Bank 2 A/F Sensor Heater open or shorted.

DTC P0036 Diagnostic Conversion Table

Model	If P0036 is stored; Diagnose as this code in the ESM
2016-2017 370Z (Coupe and Roadster)	P0051 and P0052
2016-2017 Altima with V6 engine	P0051 and P0052
2017 Armada	P0050
2016-2017 Murano	P0051 and P0052
2016-2017 Pathfinder (With V6 engine)	P0051 and P0052

NOTE: The ESMs will be updated at a later date.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.