

Fuel Filler Door Difficult To Open Or Close

Vehicle Type: **Panamera (971)**

Model Year: **2017**

Information: Fuel filler door fit to the seal is slightly closer on one end than the rest of the opening.

Symptom: The effort to open and close the fuel filler door is a little more than typically expected.

Information for Customer: The extra effort required to open and close the fuel filler door has no negative impact on the vehicle.



Information for Workshop: No repairs necessary and no warranty claims should be filed. PAG is aware of the issue and the necessary product improvements to reduce the force required to open and close the fuel diller door are in process.

Dealership	Service Manager _____	Shop Foreman _____	Service Technician _____	_____	_____	_____	_____
Distribution	Asst. Manager _____	Warranty Admin. _____	Service Technician _____	_____	_____	_____	_____
Routing							

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, Tiptronic®, VarioCam®, PCM®, PDK®, 911®, RS®, 4S®, 718®, 918 Spyder®, FOUR UNCOMPROMISED®, and the model numbers and distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. However, specifications, standard equipment and options are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. Please ask your authorized Porsche dealer for advice concerning the current availability of options and verify the optional equipment that you ordered. Porsche recommends seat belt usage and observance of traffic laws at all times.