

Vehicle Does Not Move When in Third Gear

Vehicle Type: **718 Boxster/Cayman (982)**


Model Year: **2017, built before January 20, 2017**

Part Number: See the latest version of PET for the proper part number according to vehicle variant and options.

Customer Concern: The customer states there is no drive when the vehicle is in third gear.

Information: This was caused by poor welding of the fixed gear. The fastening process has been changed.

Resolution: Replace the transmission. Refer to WM343519 for the proper replacement procedure.



Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, Tiptronic®, VarioCam®, PCM®, PDK®, 911®, RS®, 4S®, 718®, 918 Spyder®, FOUR UNCOMPROMISED®, and the model numbers and distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. However, specifications, standard equipment and options are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. Please ask your authorized Porsche dealer for advice concerning the current availability of options and verify the optional equipment that you ordered. Porsche recommends seat belt usage and observance of traffic laws at all times.