



**MODEL:** Karma Revero

**DATE:** September 2017

**TITLE:** Baseline BL1022 Release Information

---

**APPLICABILITY:** MY17 and MY18 Revero

**MARKET REGION:** North America

**PURPOSE:** This document will be used as a reference guide for technicians on information regarding Software Baseline K1-18-1022 (“BL1022”)

**There should be no action by the service personnel at a dealership or service center. This is an over-the-air update (OTA).**

**BL1022 Dealer Service Notes:**

**Advanced Driver Assistance System (ADAS):**

**Lane Departure Warning (LDW):** New logic for improved sensitivity and function now added to the system.

**Central Infotainment Unit (CIU):** Enhancements implemented throughout. Retention of settings in all applications is improved.

**Firmware Over-the-Air (FOTA):** Enhanced security and protections introduced. More accurate messaging developed to communicate success/ completions and possible errors with over-the-air updates.

**Navigation:** Map screen on the instrument panel, enhanced stabilization. Navigation map functions added. (Ability to drop a pin on the map and navigate to it.)

**Touch Panel Interface:** Better messaging available for various events.

**Audio:** Better Bluetooth performance and stability is introduced, and functional enhancements to radio and favorite selections. USB performance and fidelity improved.

**Phone usage:** Improved phone function; making and receiving calls.

**Instrument panel (DIS):** Stability Improvements and faster start-up introduced. Further improvements to the interface, multiple functional display enhancements. New safety feature added, displayed message “Unplug vehicle to start” on DIS if owner tries to enter Ready Mode when charger is plugged in.

**HVAC:** HVAC Settings enhanced to improving retention in various operating modes.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

**MODEL:** Karma Revero

**DATE:** September 2017

**TITLE:** Baseline BL1022 Release Information

Note: The CIU software ID is verified from the TPI, not Karma Sync.

The ID is **17.12.31.1** when this is installed at the Karma Automotive Moreno Valley Assembly Plant, as part of normal manufacturing.

The CIU software will be updated *over-the-air* without assistance from TSS for this release. The CIU software ID is verified from the TPI, not Karma Sync. The ID is **17.12.31.2**.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.