

smart audio system - Tone changes and fluctuations in volume

Topic number	LI82.60-P-062499
Version	5
Design group	82.60 Radio, audio, video systems
Date	05-19-2017
Validity	BR 453 smart audio system, SA code 505/562/537/561
Reason for change	Damage code and operation number added
Reason for block	

Complaint:

In FM mode the tone or volume changes.

Cause:

- Internal parameter setting

Remedy:

New software and new SCN coding.

Perform control unit programming "A2 - Radio - smart audio system (Audio)".

Note: This also resolves the complaint "smart audio system: No automatic connection with mobile phone" (LI82.70-P-063343).

Symptoms
Communication/information / Entertainment / Audio/Sound / Tone setting malfunction
Communication/information / Entertainment / Audio/Sound / Volume adjustment function error
Communication/information / Entertainment / Audio/Sound / Poor audio quality
Communication/information / Entertainment / Audio/Sound / Speed-dependent volume control (GAL) nonfunctional

Control unit/fault code		
Control unit	Fault code	Fault text
A2 - Radio - Smart Audio System (Audio) (R0_13_453)	-	-

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
54-0991			8210N EJ	8210N Function of AM/FM radio EJ - No/poor AM/FM reception

