



Service Bulletin

3-17

Section

02 - Cab Exterior

Description

Paint peel may occur on Model 579 Grill Opening Reinforcement

Release Date

6/12/2017

Introduction

Peterbilt has determined that the paint may peel at the grill opening reinforcement (GOR) on certain Model 579 vehicles. See approved repair procedure below.

Resolution

Refinish the GOR area on Model 579 vehicles demonstrating the paint peeling issue stated above. See procedure below

Warranty

Vehicles will be covered for 3 years/300,000 miles.

Peterbilt will pay for parts and labor plus applicable mark up. File a long form "**03-17**" for repairs when refinishing the GOR.

- 3.0 hours labor to refinish the GOR per SRT 053-142

- **ALL OTHER VEHICLE AREAS REQUIRING PAINT PEEL REPAIR MUST BE FILED ON A SEPARATE CLAIM.**

--	--

For Field...	Enter...
Failure Location	053-501-004
Failure Type	345
Claim Type	N
SRT 053-142	3.0 hours labor to refinish of GOR lower hood strip for peeling - Includes R&R grill, complete stripping, prime and prep, refinish and clear

Parts

See materials list within the procedure

Procedure

[3-17 GOR Refinish Procedure](#)

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2017 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).