



# Service Communication

**SC-17-05-32**

**MODEL: Karma Revero**

**DATE: October 2017**

**TITLE: Karma Sync Update Release Notes**

---

APPLICABILITY: MY17 and MY18 Revero

MARKET REGION: North America

PURPOSE: This document will be used as information concerning Karma Sync Version 2.1.4.

Dealer Service Notes:

New Procedure available through Karma Sync:

- EBCM (Electronic Brake Control Module) Calibration
- EBCM Pressure Check
- EBCM Brake Bleeding
- HVAC (Heating Ventilation Air-Conditioning) Self-test / Calibration

This new release contains an interactive version of the Service Technical Information.

Bug Fixes:

- DTC Descriptions update

Turn on or restart Karma Sync - follow the prompts to have new version installed.

Any questions or concerns with the update please contact TSS.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.