



# Preliminary Information

PIT5587 Terrain Diesel Driver Mode Control Knob will not Switch Drive Modes

## Product Investigation Review Required

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Terrain	2018	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		LH7				
Condition:		When attempting to change driver modes using the driver mode control knob the mode will not switch.				
Cause:		Current Calibration.				

### Correction:

Turn the knob to the desired position and hold for 1 second and then release.

### Service Procedure:

Engineering is investigating the matter and working to release a calibration to enhance the response of the knob.

### Version History

Version	1.0
Modified	

