



Preliminary Information

PIP5430B TAC Part Restriction - E41 ECM Part Number 12683624

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017 - 2018	All	All	6.6 L5P	All
GMC	Sierra	2017 - 2018	All	All	6.6 L5P	All
Involved Region or Country	North America					
Additional Options (RPO)	L5P					
Condition	As part of our ongoing quality improvement efforts the 2017 and 2018 Chevrolet Silverados and GMC Sierras equipped with the 6.6L Diesel engine (RPO L5P) E41 ECM Engine Control Module Part number 12683624 will be placed on a parts restriction through the Technical Assistance Center (TAC).					
Cause	This parts restriction will assist Engineering with product feedback.					

If you require an engine control module (ECM) for a 2017 or 2018 Chevrolet Silverado or GMC Sierra equipped with the 6.6L Diesel engine (RPO L5P), please complete the following diagnostic questionnaire before you contact TAC.

Is the Restricted part being requested for customer pay? Yes/No

List all DTCs: Are the current (active) DTCs repeatable?

If DTC P0606 is found; please refer to the latest version of bulletin 17-NA-132 (Information on Malfunction Indicator Lamp (MIL) Illuminated - DTC P0606 Set)

If any turbocharger or fuel related DTCs are set; check for leaks in the air and/or fuel systems. Leaks in the air or fuel system may cause DTCs to set.

What is the battery voltage reading?

Have you completed the appropriate SI documents for the DTCs listed?

What SI documents were used for diagnosis?

What step in the SI document led to replace the ECM?

Parts Information

Description	Part Number	QTY
ECM	12683624	1

Warranty Information

Labor Operation	Description	Labor Time
4025390	Engine Control Module Replacement	1.0

Version History

Version	3
Modified	5/4/2017 - Added information about DTC P0606 and bulletin 17-NA-132 10/06/2017 - Added 2018 model year and deleted part number 12670950.



© 2016 General Motors. All Rights Reserved.