



# Preliminary Information

## PIT5588 Water Leak In Bed Area On Trucks With High Desert Package

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017 - 2018	All	All	All	All
Involved Region or Country		North America				
Additional Options (RPO)		High Desert Edition (ZYD)				
Condition		Some customers may comment that the bed area is not water tight or that water is leaking between the removable tonneau panels and along the edges.				

The design intent of the High Desert Package is not to provide a water tight cargo area.

The package is designed to have a water management system but some water may still migrate into the bed area.

We are evaluating improvement to the system to reduce the amount of water migrating into the bed to an acceptable level.

Please communicate to the customer that we apologize for this inconvenience.

Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

Dealers should submit a product report on each of the complaint vehicles so that they can be tracked for future resolution.

Refer to the latest version of Corporate Bulletin Number 02-00-89-002 (Information for Dealers on How to Submit a Field Product Report).

Canadian dealers should refer to the latest version of Corporate Bulletin Number 10-00-89-006.

### Version History

Version	1
Modified	

