



# Preliminary Information

PIT5590 Service Driver Assist System Message with B172E stored in history

## Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018	All	All	All	All
Buick	Envision	2017 - 2018	All	All	All	All
Buick	Lacrosse	2017 - 2018	All	All	All	All
Cadillac	CT6	2017 - 2018	All	All	All	All
Cadillac	XT5	2017 - 2018	All	All	All	All
Chevrolet	Equinox	2018	All	All	All	All
GMC	Acadia	2017 - 2018	All	All	All	All
GMC	Terrain	2018	All	All	All	All

Involved Country/Region	North America
Additional RPO	N/A
Condition	Customer may comment that they received an intermittent "Service Driver Assist System" DIC message and/or vehicle has a B172E or B172F Code Stored in history in the MSM. B172E or B172F is being set as a phantom code due to an electrical backfeed.
Cause	N/A

## Correction:

Do not replace any parts. Explain to customer that Engineering is aware of the issue and a new control module with added diodes to address this phantom code is in development and will be available Q1 2019.

## Warranty Information

Labor Operation	Description	Labor Time
7080488	Checking system, clearing codes and discussing with customer	Use Published Labor Operation Time

