

Preliminary Information

PIP5518B Rattle Or Pop Noise During Gas Engine Start

Models

| Brand: | Model: | | Model Years: | VIN: | | Engine: | Transmissions: | |
|--|--------|---|--------------|------|-----|-----------|-----------------|--|
| Biana. | | | | from | to | Liigilie. | riansinissions. | |
| Chevrolet | Volt | | 2016 - 2018 | All | All | 1.5L L3A | All | |
| Involved Region or Country North America | | | | | | | | |
| Additional Options (RPO) | | None | | | | | | |
| Condition | | Rattle Or Pop Noise During Gas Engine Start | | | | | | |
| Cause | | Under Investigation At This Time. | | | | | | |

Correction:

Some customers may have a concern of a rattle or pop noise during gas engine start.

This concern only occurs on low speed tip in type maneuvers.

It would normally be duplicated during stop go traffic type of situations where the engine starts in the 2000 rpm range.

This issue will not occur on zero vehicle speed starts or during high pedal input starts.

This issue will not cause any damage to the propulsion or vehicle systems.

GM is currently validating a correction for this concern that will be available in the second quarter of 2018.

If no codes or other symptoms are present, do not attempt repairs or replace any components for this concern.

This PI will be updated with additional details as they become available.

Version History

| | 3 | | | | |
|---------|--|--|--|--|--|
| Version | 9/15/2017 – Updated Correction Section. | | | | |
| | 10/18/2017 - Updated repair section information. | | | | |















