



Preliminary Information

PIT5592 Rear Camera Screen Bright at Night

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Canyon	2018	All	All	All	All
Chevrolet	Colorado	2018	All	All	All	All
Chevrolet	S10 (Export)	2018	All	All	All	All
Chevrolet	Trailblazer (Export)	2018	All	All	All	All
Involved Region or Country	North America and Brazil					
Additional Options (RPO)	IO5/IO6					
Condition	Some customers may comment that the rear camera display is too bright at night.					
Cause	This condition may be caused by a software anomaly.					

Correction:

If this concern is encountered, check for codes and evaluate rear camera operation by covering and uncovering the ambient light sensor while at a stop and in reverse to determine if the display stays bright when covered. If the display stays bright and there are no related codes to diagnose, do not replace any parts as engineering is currently evaluating the concern. If a service fix is released, a service bulletin will be released/updated with repair instructions.

Warranty Information

Labor Operation	Description	Labor Time
3480638	Evaluate Rear Vision Camera Brightness and Check for Codes	.3
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	

