



17-2207

TECHNICAL SERVICE BULLETIN

Tire/Wheel Vibration At Highway Speeds Above 80 Km/h (50 MPH)

19 October
2017

This bulletin supersedes 16-0142. Reason for update: Concern Carryover to New Model

Model:

Ford 2017-2018 Escape

Summary

This article supersedes TSB 16-0142 to update the vehicle model years.

Issue: Some 2017-2018 Escape vehicles may exhibit a vibration at highway speeds above 80 Km/h (50 MPH) which may be attributed to short term flat spotting in the tires.

Action: Follow the Service Procedure steps to correct the condition.

Warranty Status: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2017-2018 Escape: Visually Inspect, Adjust Tire Pressure Includes Time To Road Test (Do Not Use With Any Other Labor Operations)	172207A	0.6

Repair/Claim Coding

Causal Part:	1508
Condition Code:	D9

Service Procedure

1. Visually inspect the tires for possible damage. Are any concerns present?
 - (1). Yes - this article does not apply. Refer to Workshop Manual (WSM), Section 204-04.
 - (2). No - proceed to Step 2.
2. Check and adjust tire pressures to placard specification.
3. Drive the vehicle to confirm customer concern. The vehicle must be driven a minimum of 15 miles to eliminate any temporary flat spotting conditions. Is the vibration still present?
 - (1). Yes - this article does not apply. Refer to WSM, Section 204-04.
 - (2). No - no further action required. Return the vehicle to the customer.

© 2017 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides

information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.