



Preliminary Information

PIP5510C DTC P20EE - Diagnostic Procedure for SCR System

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017 - 2018	All	All	6.6 L5P	All
GMC	Sierra	2017 - 2018	All	All	6.6 L5P	All
Involved Region or Country:		North America and Israel				
Condition:		A dealer may encounter a customer concern of the Malfunction Indicator Lamp (Check Engine Light) coming on.				
Cause:		Diagnostics may show that DTC P20EE has set.				

Correction:

Complete the current SI diagnostic for any trouble code or symptom found. If SI diagnostics does not resolve the concern or if the results are inconclusive please refer to campaign [17337](#).

Enhancements for DTC P20EE diagnostics are included in the ECM software update referred to in campaign [17337](#).

Version History

Version	3
Modified	<p>8/24/2017 to add 2018, information about reductant temperature and re-arrange the order of the diagnostic steps.</p> <p>9/28/2017 to remove step 7 of the procedure. Step 7 is now covered by the DTC P20EE flow chart in SI.</p> <p>11/2/2017 to refer to calibration updates found in campaign 17337.</p>

