

### Instrument Cluster TFT Displays Inactive

Vehicle Type: **Panamera (971)**

Model Year: **2017 - 2018**

Customer Concern: The customer reports that the left and right instrument cluster TFT displays do not function. (See figure 1.)

Technical Concern: This failure is often accompanied by a long list of instrument cluster faults, including "C11011 - Control unit faulty, watchdog". All reported cases have been at PDI or with very low mileage.



Figure 1

Service Information: The recommended repair is to replace the instrument cluster. Only part numbers with suffix "G" or later should be used.

As always, be sure to document the complaint completely in PQIS. For this repair, use the following coding for the cause:

**Cause Location:** 90250 Instrument cluster

**Cause Symptom:** 4042 No display

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, Tiptronic®, VarioCam®, PCM®, PDK®, 911®, RS®, 4S®, 718®, 918 Spyder®, FOUR UNCOMPROMISED®, and the model numbers and distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. However, specifications, standard equipment and options are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. Please ask your authorized Porsche dealer for advice concerning the current availability of options and verify the optional equipment that you ordered. Porsche recommends seat belt usage and observance of traffic laws at all times.