

TOL NOTICE (US&CAN) – September 14, 2017

**Service Bulletin 551
Street Triple Coolant Tee Piece Torque Change**

Triumph has released **Service Bulletin 551** regarding the need to increase torque figure of the fixings securing the coolant tee piece to the lower crankcase on the below listed Street Triple models.

SERVICE BULLETIN 551: Coolant Tee Piece Torque Change		
Bulletin Number	Models Affected	VIN Range
551	Street Triple S	From 803572 to 853473
	Street Triple R	From 806646 to 853473
	Street Triple R LRH	From 822626 to 853473
	Street Triple RS	From 800262 to 853473

Dealers are requested to torque the fixings as described in the procedure below.

Bulletin Number	Fault Code	Repair Code	Description	Repair Time Allowance
551	21035933	99551	Increase the torque of M6 x 1.0 x 25 fixings from 6 Nm to 10 Nm	0.03 hours

Note: Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. The modified motorcycles can be identified by checking the ‘Outstanding Service Bulletins’ on Warranty Online.

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 551) or the attached **Service Bulletin 551 PDF** for complete instructions. Please ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the “VIN Enquiry” function within TOL (found under the **Service / Technical** drop down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership. For more information, please contact Triumph 24/7 Customer Support at (888) 284-6288.

TRIUMPH MOTORCYCLES AMERICA