

TOL NOTICE (US&CAN) – September 26, 2017

Service Bulletin 550: Street Scrambler Control Plate Washers

Triumph has released **Service Bulletin 550**. Internal investigations have identified that washers may need to be fitted to the fixings securing the left hand control plate on the below listed models.

SERVICE BULLETIN 550: Street Scrambler Control Plate Washers		
Bulletin Number	Models Affected	VIN Range
550	Street Scrambler	From 842556 to 848714

Dealers are requested to check for the fitment of washers and, if required, install the washers as described in the procedure below.

Bulletin Number	Fault Code	Repair Code	Description	Repair Time Allowance
550	20830950	99550	Fit left hand control plate washers	0.05 hours

Note: Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. The modified motorcycles can be identified by checking the 'Outstanding Service Bulletins' on Warranty Online.

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 550) or the attached **Service Bulletin 550 PDF** for complete instructions. Please ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the “VIN Enquiry” function within TOL (found under the **Service / Technical** drop down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership. For more information, please contact Triumph 24/7 Customer Support at (888) 284-6288.

TRIUMPH MOTORCYCLES AMERICA