

TOL NOTICE (US&CAN) – May 5, 2017

New Diagnostic Software Available for Download

Diagnostic software version [2017-5](#) is now available to download. Dealers should download this update and begin using immediately.

*Download password has not changed (case sensitive): **Custom27***

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.



SUMMARY OF CHANGES:

Replacement Instrument Calibrations

- 8 Replacement TFT instrument calibrations for Street Triple R and RS models to resolve an instrument bug with TPMS functionality.

Calibration Description Corrections

- Correct the calibration description of 20186 for America models (use with aftermarket silencers and mechanical odometer) to match 20186 for Speedmaster models (use with aftermarket silencers and mechanical odometer). Fuel up to E25. Minimum 91 RON (87 RON/MON) fuel).

Bug Fix(es)

- Resolved a bug where the calibration description was not displayed when the same calibration file is used more than once in the software with different calibration descriptions. The software was unable to determine which calibration description to use thus generating the reported error.
Note: ECMs that do not contain a valid VIN (replacement ECMs) will still display this behaviour. This is not considered a bug, and will be resolved in a future update.

If you have any questions, please contact Triumph 24/7 Customer Support at (888) 284-6288.

TRIUMPH MOTORCYCLES AMERICA