



Countries: BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, MEXICO, ARUBA, NICARAGUA, PERU, Curaçao, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, PANAMA

Document ID: IK0700101

Availability: ISIS, NotSIR

Revision: 1

Major System: EXHAUST

Created: 10/3/2017

Current Language: English

Last Modified: 11/3/2017

Other Languages: NONE

Author: Jason Heckler

Viewed: 118

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		View My Bookmarks				1	1

Title: LT/ Prostar Exhaust Stack Heat Shield Crack

Applies To: A26, ISX15, LT and Prostar Chassis with 07BER

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

11/03/2017 - Minor formatting changes. Added warranty noun coding.
11/02/2017 - Initial Article Release

DESCRIPTION

This document will guide the user through identifying exhaust heat shield cracking and the repair method.

SYMPTOM(s)

Diagnostic Trouble Code(s) & Dashboard Indicator Light(s)

DTC/Light	Description
N/A	

Customer Observations or Concerns:

Exhaust stack heat shield cracked at bolt hole(s).

SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
N/A			

[Tools Resource Center](#)

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes
Heat Shield	Per lineset	1	
BOLT, SEMS M8 X 1.25-35MM (Stainless Steel bolt and washer)	3804756C1	6	

REPAIR STEP(s)

 WARNING:
Exhaust system will retain excessive heat, use precaution when handling or working on any components thereof. Proper cooling before work performed and Personal Protective Equipment is required.

Step	Action	Decision
1	DIAGNOSTIC: Is the exhaust heat shield cracked (Figure 1)?	Yes. Continue to Step 2.
		No. Article does not apply



Figure 1: Heat Shield crack

Step	Action	Decision
2	Replace the heat shield with lineset heat shield, install bolt and washer contained in kit (3804756C1)	Continue to Step 3

Step	Action	Decision
3		

Torque the six exhaust shield mounting bolts to the following specs, 17Ft LBS or 204 inch LBS.

Repair completed

WARRANTY INFORMATION

Warranty Claim Coding:

Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.

Group	Noun
07015	426

Standard Repair Time(s):

Refer to the [SRT Manual](#) for Repair Times

OTHER RESOURCES

[Master Service Information Site](#)

 Hide Details

Feedback Information

Viewed: 117

Helpful: 1

Not Helpful: 1

No Feedback Found