



# Service Bulletin

File in Section: -


Bulletin No.: 17-NA-234

Date: July, 2017

## TECHNICAL

**Subject:** Elevation Edition Equipped with Wrong Rear Bumper

Brand:	Model:	Model Year:		Date Breakpoint:		Engine:	Transmission:
		from	to	from	to		
GMC	Sierra Models	2017	2017	SOP	Prior to December 1, 2016	All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPOs)</b>	Equipped with SALES PACKAGE - ELEVATION EDITION (SXL), PRIMARY COLOR - EXTERIOR, GASOLINE MET-2 (GPA) and <b>minus</b> REAR PARK ASSIST (- UD7).
<b>Condition</b>	Some customers may notice sensors are present on the rear bumper and assume the rear park assist feature is available, but inoperative.
<b>Cause</b>	<div style="text-align: center;">  </div> <p style="text-align: right;">4830979</p> <p>The cause of the condition may be that vehicles were incorrectly over-built from the plant with rear bumpers containing unrequired, non-functional sensors.</p>
<b>Correction</b>	Replace the rear bumper assembly with the Non - UD7 rear bumper listed in the Part Table below. Refer to <i>Rear Bumper Impact Bar Replacement</i> in SI.

**Parts Information**

Description	Part Number	Qty
BAR-RR BPR IMP*	23285673	1
Replacement bumper is: PAINT TO MATCH, DOES NOT HAVE SENSOR HOLES		

**Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1421710	Rear Bumper Impact Bar Replacement	Use Published Labor Operation Time

Version	1
Modified	

