	GROUP <b>Service Campaign</b>	MODEL <b>2015-2017MY K900 (KH)</b>
	NUMBER <b>SC156</b>	DATE <b>November 2017</b>
<b>VOLUNTARY SERVICE CAMPAIGN</b>		
SUBJECT: SEAT BELT ANCHOR PRETENSIONER COVER WARNING LABEL APPLICATION (SC156)		

This bulletin provides information for applying a warning label to the front right and left side seatbelt anchor pretensioner covers on all 2015-2017MY K900 (KH) vehicles produced from December 18, 2013 through May 18, 2017. The warning label shows the proper position of the lock nut slot. During a collision repair or other repair involving either of these components, the service procedure listed on the label must be followed. If this procedure is not followed, there is a chance that the connection would not be fully locked. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



**\* NOTICE**

To assure complete customer satisfaction, always remember to refer to WebDCS Warranty Coverage (validation) Inquiry Screen (Service → Warranty Coverage → Warranty Coverage Inquiry) for a list of any additional campaigns that may need to be performed on the vehicle before returning it to the customer.

File Under: <Service Campaign>

- Circulate To:     General Manager     Service Manager     Parts Manager  
 Service Advisors     Technicians     Body Shop Manager     Fleet Repair


SUBJECT:

# SEAT BELT ANCHOR PRETENSIONER COVER WARNING LABEL APPLICATION (SC156)

## Seat Belt Pretensioner Warning Label Application Procedure:

**NOTE: The work procedure is the same for the LH/RH sides.**

1. Locate the front LH/RH Seat Belt Pretensioners (A).



2. Apply the LH warning label to the LH pretensioner surface. Do not apply the sticker over any felt covered surface.

**NOTE: Be sure the surface of the pretensioner is clean before applying the warning label.**



3. Repeat step 2 for the RH pretensioner warning label.



Sample Applied Label



SUBJECT:

## SEAT BELT ANCHOR PRETENSIONER COVER WARNING LABEL APPLICATION (SC156)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
K900 (KH)	December 18, 2013 to May 18, 2017

REQUIRED PART:

Part Name	Part Number	
	LH	RH
Anchor Pretensioner Linkage Label Kit		
	88857 3T500QQK	

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
R	52123 3E750	0	(SC156) Warning Label Application of Front LH/RH Seat Belt Anchor Pretensioner	170100R0	0.2 M/H	88857 3T500QQK	1

### \* NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SC156 when accessing the WebDCS system.