



Preliminary Information

PIC6317 Information On Hazard Lamps Being Inoperative After The Instrument Panel Accessory Bezel Was Removed

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore	2017	All	All	All	All

Involved Country or Region	North America
Condition	Hazard Lights are inoperative.
Cause	The hazard switch or other switches can become disconnected or damaged during the removal of the instrument panel accessory bezel. Reports have shown that customers have returned for this concern after a previous repair in which the bezel had to be removed.

Correction:

When removing the instrument panel accessory bezel, disconnect the electrical connectors from the switches.
When installing the bezel insure all connectors are fully seated. After installation check all electrical functions to insure all buttons operate normally.

Version History

Version	1
Modified	

