



Preliminary Information

PIT5603 Cannot Learn Steering Angle Or Torque Sensor After Replacing The Steering Column

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2008 - 2009	All	All	All	All
Pontiac	Torrent	2007 - 2008	All	All	All	All
Saturn	Vue	2008 - 2009	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		None				
Condition:		Cannot Learn Steering Angle Or Torque Sensor After Replacing The Steering Column				
Cause:		Engineering is investigating this concern.				

Engineering is aware of this concern and is investigating an issue with the steering column. No other parts should be replaced attempting to repair. This PI will be updated when a repair is available.

Version History

Version	1.0
Modified	

