



# Preliminary Information

## PIP5481B Check Engine Light On With DTC P026A and a Snow Plow Installed

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017 - 2018	All	All	6.6 L5P	All
GMC	Sierra	2017 - 2018	All	All	6.6 L5P	All
Involved Region or Country	North America					
Additional Options (RPO)	6.6 L5P					
Condition	Some customers may comment on a Service Engine Soon Light / Check Engine Light on. Technician may find DTC P026A and a snow plow installed.					
Cause	If vehicle exceeds 72 km/h (45 MPH) the vehicle could overheat and be damaged					

### Correction:

Please refer to the owner's manual under Adding a Snow Plow or Similar Equipment (In Service Information it will be Document ID 4501631). It states:

**Caution: Do not exceed 72 km/h (45 mph) with a snow plow mounted to the vehicle. The vehicle could overheat and be damaged.**

### Version History

Version	3
Modified	8/31/2017 to add 2018 model year. 12/20/2017 to remove that the concern is under investigation.

