
	GROUP BOD	MODEL 2016MY Cadenza (VG)
	NUMBER 171	DATE December 2017
TECHNICAL SERVICE BULLETIN		
SUBJECT: CLUSTER FASCIA PANEL REPLACEMENT		

This bulletin provides information regarding the replacement of the cluster fascia panel on some 2016MY Cadenza vehicles, produced from March 16, 2015 through January 1, 2016, which may exhibit wrinkles or deformation. Follow the procedure outlined in this bulletin to replace the cluster fascia panel with an improved part.



File Under: <Body>

-
- Circulate To:**
 General Manager
 Service Manager
 Parts Manager
 Service Advisors
 Technicians
 Body Shop Manager
 Fleet Repair

SUBJECT: CLUSTER FASCIA PANEL REPLACEMENT

Replacement Procedure:


1. Replace the cluster fascia panel by referring to the “Body (Interior and Exterior) → Interior → Crash Pad → Repair procedures” chapter in the applicable Shop Manual on KGIS.



AFFECTED VEHICLE RANGE:

Model	Production Date Range
Cadenza (VG)	March 16, 2015 through January 1, 2016

REQUIRED PART:

Part Name	Part Number	Figure
Cluster Fascia Panel	84830 3RAC0CAFFF	

WARRANTY INFORMATION:

N Code: B19 C Code: ZZ8

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
W	84830 3RAC0CA	0	Cluster Fascia Panel Replacement	84811R00	0.2 M/H	84830 3RAC0CAFFF	1