
	GROUP ENG	MODEL 2018MY Stinger (CK)
	NUMBER 182	DATE December 2017
TECHNICAL SERVICE BULLETIN		
SUBJECT: SERVICE ACTION: EMISSIONS LABEL REPLACEMENT (SA324)		

This bulletin provides the procedure to replace the Emissions Label on some 2018MY Stinger (CK) vehicles equipped with Theta 2.0-T engines, produced from September 29, 2017 through November 20, 2017, which contains incorrect emissions information on both RWD and AWD models. Follow the procedure outlined in this bulletin to adhere the new revised emissions label. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.

Incorrect Emissions Labels

 KIA MOTORS CORPORATION VEHICLE EMISSION CONTROL INFORMATION		
Conforms to regulations : 2018 MY		
U.S.EPA : T3B125 LDV	OBD : CA II	Fuel : Gasoline
California : LEV III ULEV125 PC	OBD : CA II	Fuel : Gasoline
No adjustments needed.	DFIWR-HO2S/HO2S/WU-TWC/TWC/CAC	
Group : JKMXV02.04X6	A22	32431-2CCA0
Evap : JKMXR0140DYE		

(RWD)

 KIA MOTORS CORPORATION VEHICLE EMISSION CONTROL INFORMATION		
Conforms to regulations : 2018 MY		
U.S.EPA : T3B125 LDV	OBD : CA II	Fuel : Gasoline
California : LEV III ULEV125 PC	OBD : CA II	Fuel : Gasoline
Group : JKMXV02.04X6	DFIWR-HO2S/HO2S/WU-TWC/TWC/CAC	
Evap : JKMXR0140DYE	No adjustments needed.	A24
	32431-2CCB0	
[WARNING] Loaded IM testing of permanent four-wheel drive or traction control-equipped vehicles must be conducted on a four-wheel drive speed synchronized dynamometer. Otherwise a non-loaded test procedure must be performed.		

(AWD)

* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA324.

File Under: <Engine>

- Circulate To:**
- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> General Manager | <input checked="" type="checkbox"/> Service Manager | <input checked="" type="checkbox"/> Parts Manager |
| <input checked="" type="checkbox"/> Service Advisors | <input checked="" type="checkbox"/> Technicians | <input checked="" type="checkbox"/> Body Shop Manager |
| | | <input checked="" type="checkbox"/> Fleet Repair |

SUBJECT: SERVICE ACTION: EMISSIONS LABEL REPLACEMENT (SA324)

Replacement Procedure:

1. Open the engine compartment hood and locate the vehicle emissions label underneath the hood assembly.



2. With an alcohol wipe or equivalent cleaner, clean the surface of the existing emissions label from contaminants and debris.

*** NOTICE**
 Failure to clean the surface will prevent the new label from adhering properly.

3. Carefully center and affix the new provided emissions label over the existing label on the hood assembly.

*** NOTICE**
 Note that the RWD and AWD models require different labels.

--	--

Before (RWD)

After (RWD)

--	--

Before (AWD)



After (AWD)

SUBJECT: SERVICE ACTION: EMISSIONS LABEL REPLACEMENT (SA324)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Stinger (CK)	September 29, 2017 through November 20, 2017

REQUIRED PART:

Part Name	Part Number	Figure
Emissions Label (RWD)	32431 2CCA1	 <p>KIA MOTORS CORPORATION VEHICLE EMISSION CONTROL INFORMATION Conforms to regulations: 2018 MY U.S.EPA: T3B125 LDV OBD: CA II Fuel: Gasoline California: LEV III ULEV125 PC OBD: CA II Fuel: Gasoline No adjustments needed. DF1WR-HQ2SHQ2SWU-TWC7C/CAC Group: JKMXXV2.04X6 Evap.: JKMXR0140DYE AA22 32431-2CCA1</p>
Emissions Label (AWD)	32431 2CCB1	 <p>KIA MOTORS CORPORATION VEHICLE EMISSION CONTROL INFORMATION Conforms to regulations: 2018 MY U.S.EPA: T3B125 LDV OBD: CA II Fuel: Gasoline California: LEV III ULEV125 PC OBD: CA II Fuel: Gasoline Group: JKMXXV2.04X6 Evap.: JKMXR0140DYE No adjustments needed. 32431-2CCB1 AA24 [WARNING] Loaded IM testing of permanent four-wheel drive or traction control-equipped vehicles must be conducted on a four-wheel drive speed synchronized dynamometer. Otherwise, a non-loaded test procedure must be performed.</p>

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	32431 2CCA0	0	(SA324) Emissions Label Installation	170125R0	0.2	32431 2CCA1	1
						32431 2CCB1	

* NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference **SA324** when accessing the WebDCS system.