

MODEL: Karma Revero**DATE:** December 2017**TITLE:** Back Lite Seal Lubricant Application**First Release****PRIORITY:** On Complaint**APPLICABILITY:** MY17 and MY18 Revero**MARKET REGION:** North America**PURPOSE:** Remedy for a trunk squeak on opening

If the trunk lid exhibits a loud squeak on opening, an application of lubricant along the backlite seal is found to remedy this. (Use Nextzett, Gummi Pflege Stift)



fig 1

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

DATE: December 2017

First Release

TITLE: Back Lite Seal Lubricant Application

Apply the Gummi Pflege Rubber Care lubricant to the seal lip along the entire length (fig 2a)
 Apply to both surfaces of the seal as shown in (fig 2b and 2c).



fig 2a




fig 2b

Ensure squeak is gone or minimized before returning to the customer.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.



Technical Service Bulletin

TB-17-76-34

MODEL: Karma Revero

DATE: December 2017

First Release

TITLE: Back Lite Seal Lubricant Application

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY
Source Locally	Nextzett, Gummi Pflege Stift	1

SHOP SUPPLIES:

DESCRIPTION
N/A

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART:

PART NUMBER	DESCRIPTION

LABOR CODES:

CODE	DESCRIPTION	TIME	DEFECT CODE
76-20-01-05	Lubricant Application	0.2	76-20-01-20

SUBLET:

CODE	DESCRIPTION	AMOUNT
MSC	Nextzett, Gummi Pflege Stift	max \$20.00

WARRANTY DISPOSITION: This repair is covered under the New Vehicle Limited Warranty, in effect for five (5) years from the in-service date with no mileage limitation.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.