

SERVICE ACTION

Reference number:	SA-14-0294	Issued: 08 December, 2017
Subject:	Replace the Trickle Charge Connection Assembly (Battery Conditioner Socket)	
Model(s):	DB11	
VIN range:	Refer to the separately published list of Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Action

Some DB11 vehicles do not have the correct trickle charge connection assembly installed. If an incorrect trickle charge connection assembly is installed, it can be difficult to connect the trickle charger (battery conditioner) to the trickle charge connection assembly. Do the procedure that follows to install the correct trickle charge connection assembly on all applicable vehicles.

Workshop Procedure

1. Remove the trickle charge connection assembly (refer to Workshop Manual procedure 14.01.EC).

Note: *Make sure that the new trickle charge connection assembly has "12v" written on it.*

2. Install the new trickle charge connection assembly (refer to Workshop Manual procedure 14.01.EC).

Part Data

Description	Part Number	Quantity
Trickle Charge Connection Assembly	HY53-6D612-AA	1

Warranty Data

Procedure and Labour Time

Description	Labour Time
Trickle Charge Connection Assembly - Remove and Install New Part.	1.75 hours

Please Note:

When you have completed this Service Action, make sure that you make an entry in Section A of the Vehicle Owner's Guide to show that the procedure is completed.

If you have any questions related to this Service Action, please contact: Aston Martin Technical Services on: +44 (0) 1926 644720, email: askamtech@astonmartin.com, or contact your After Sales Manager.

The English version of this Service Action is written in Simplified Technical English to ASD-STE100™.