

QUARANTINE NOTICE

Reference number:	QN-14-0072	Issued: 08 December, 2017
Subject:	Replace the Trickle Charge Connection Assembly (Battery Conditioner Socket)	
Model(s):	DB11	
VIN Range:	Refer to the separately published list of Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Note: *This repair is the same as Service Action SA-14-0294. Use this Quarantine Notice for vehicles that are not registered and have not been given to a Customer.*

Some vehicles in the affected VIN list for this Quarantine may now be registered and given to a Customer. Make sure that you do a check of the Online Dealer Warranty (ODW) database to make sure that all necessary work is done to every vehicle.

Reason for this Quarantine Notice

Some DB11 vehicles do not have the correct trickle charge connection assembly installed. If an incorrect trickle charge connection assembly is installed, it can be difficult to connect the trickle charger (battery conditioner) to the trickle charge connection assembly. Do the procedure that follows to install the correct trickle charge connection assembly on all applicable vehicles.

Workshop Procedure

1. Remove the trickle charge connection assembly (refer to Workshop Manual procedure 14.01.EC).

Note: *Make sure that the new trickle charge connection assembly has "12v" written on it.*

2. Install the new trickle charge connection assembly (refer to Workshop Manual procedure 14.01.EC).

Part Data

Description	Part Number	Quantity
Trickle Charge Connection Assembly	HY53-6D612-AA	1

Warranty Data

Procedure and Labour Time

Description	Labour Time
Trickle Charge Connection Assembly - Remove and Install New Part.	1.75 hours

If you have any questions related to this Quarantine Notice, please contact: Aston Martin Technical Services on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
Or contact your After Sales Manager.

The English version of this Quarantine Notice is written in Simplified Technical English to ASD-STE100™.