

SSM  
46922

Some 2018 EcoSport vehicles equipped with a Ford Accessory remote start feature may exhibit an illuminated wrench indicator along with a See Manual message on the information display in the IPC. This may be due to the key takeover process being initiated during the remote start session. Do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.