

LTB01121NAS1



# TECHNICAL BULLETIN

22 DEC 2017

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

## INFORMATION

---

---

### SECTION:

501-12: Instrument panel and console

---

### SUBJECT/CONCERN:

Front Stowage Compartment Does Not Open

---

### AFFECTED VEHICLE RANGE:

| MODEL: | MODEL YEAR: | VIN: | ASSEMBLY PLANT: |
|--------|-------------|------|-----------------|
|        |             |      |                 |

| MODEL:         | MODEL YEAR:  | VIN:           | ASSEMBLY PLANT: |
|----------------|--------------|----------------|-----------------|
| Discovery (LR) | 2017 Onwards | 000532 Onwards | Solihull        |

---

## MARKETS:

NORTH AMERICA

---

## CONDITION SUMMARY:

### SITUATION:

The front stowage compartment, located behind the Integrated Control Panel (ICP), may not open.

### CAUSE:

This may be caused by a potential clash of components and/or the incorrect routing of electrical harnesses.

### ACTION:

Should a customer express this concern, follow the Service Instruction below.

---

## PARTS:

| PART NUMBER | DESCRIPTION  | QUANTITY |
|-------------|--------------|----------|
| LR113781    | Nylon washer | 2        |

---

## WARRANTY:

### NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

| DESCRIPTION   | SRO         | TIME<br>(HOURS) | CONDITION<br>CODE | CAUSAL<br>PART |
|---|-------------|-----------------|-------------------|----------------|
| Front stowage compartment -<br>Modification           | 76.13.89.47 | 0.1             | 12                | LR081202       |
| Front stowage compartment -<br>Inspect/Adjust - Left  | 76.13.89.45 | 0.1             | 12                | LR081202       |
| Front stowage compartment -<br>Inspect/Adjust - Right | 76.13.89.46 | 0.1             | 12                | LR081202       |
| Replace instrument panel trims                        | 76.25.85    | 0.1             | 12                | LR081202       |

**NOTE:**

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

- 1 Diagnose and repair the customer concern (see TOPIx Workshop Manual section 501-12: Instrument panel and console - Diagnosis and testing - Front stowage compartment access issues - Remedial advice).