



Technical Tip

Topic	01-15-07TT – MIL ON, DTC P1386 Control Module Faulty
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	July 21, 2017

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

MIL ON, DTC P1386 Control Module Faulty

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Passat, Golf, Beetle, Beetle Convertible	2011-2014	2.5L (CBTA/CBUA)	All	All	All

Technical Background

NA.

Service

In the event of fault code P1386 setting in the ECM, replace the -**G28**- (engine crankshaft speed sensor).

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2042345/4	7/21/17	Update to include Beetle and Beetle Convertible applicability.
2042345/3	6/22/17	Update to latest standard.
2042345/2	11/13/15	Correction to Fault Code.
2042345/1	11/6/15	Original publication.

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.