



Technical Journal

TITLE:
Low pressure sensor (LPS) updated method

REF NO: TJ 32697.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-10-13	STATUS DATE: 2017-10-19
FUNC GROUP: 2349	FUNC DESC: Miscellaneous	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ 32697.pptx	0.8225 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
13X	26	B4204T12					2017-9999		-	201617-999952
13X	40	B4204T11					2017-9999		-	201617-999952
13X	49	B4204T9					2017-9999		-	201617-999952
15X	40	B4204T11					2017-9999		-	201617-999952
15X	49	B4204T9					2017-9999		-	201617-999952
15X	A0	B4204T43					2017-9999		-	201617-999952
23X	10	B4204T23					2017-9999		-	201617-999952
23X	A2	B4204T27					2018-9999		-	201617-999952
23X	BC	B1BPHEV					2018-9999		-	201717-999952
24X	10	B4204T23					2018-9999		-	201718-999952
24X	A2	B4204T27					2018-9999		-	201718-999952
24X	BA	B1APHEV					2018-9999		-	201718-999952
24X	BC	B1BPHEV					2018-9999		-	201718-999952
24X	BR	B1FPHEV					2018-9999		-	201718-999952
25X	10	B4204T23					2017-9999		-	201617-999952
25X	A2	B4204T27					2017-9999		-	201617-999952
25X	BA	B1APHEV					2017-9999		-	201617-999952



Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
25X	BC	B1BPHEV					2017-9999		-	201617-999952
25X	BR	B1FPHEV					2018-9999		-	201717-999952

CSC Customer Symptom Codes

Code	Description
7G	Text window and warning symbol/Yellow symbol and text message
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

VST Operation Number

VST Operation Number	Description
28405-2	Pressure sensor fuel line (LPS replace)

DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

If the fuel low pressure sensor (LPS) needs replacement, see updated information under service.

SERVICE:

This TJ is released to inform that a method is changed in VIDA regarding replacement of fuel low pressure sensor (LPS).

There are two different methods in VIDA depending on version of fuel low pressure sensor (LPS), see attached document.

The method in VIDA can be found if searching for VST operation 28405-2.

VEHICLE REPORT:


Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 2349.

To view TJ attachment continue to next page. This TJ has one attachment.

TJ 32697



A



B

