

Technical Service Bulletin

64 Faint images appear in windshield

64 17 40 2047061/1 March 2, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2013 - 2020	All	Not Applicable

Condition

At certain sunlight entry angles or with fog on the inside of the windshield faint images can be seen. The images vary from production sticker afterimage or an image of the suction cups used to install the windshield in production.

Technical Background

Residue from suction cups or labels can transfer to the glass and, while not visible under normal conditions, can be seen under certain lighting or moisture conditions (Figure 1).



Figure 1. Faint images on window.

Technical Service Bulletin

Production Solution

Not applicable.

Service

This residue can be removed using the cleaning cloth (Figure 2) from the window seal set D 096 330 A2. Apply moderate pressure while cleaning.



Figure 2. Cleaning cloth from the D 096 330 A2 window seal set.



Note:

Only use the cleaning cloth. Do not use the applicator that is included in this kit for this purpose.



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	6414		
Damage Code:	0030		
Labor Operations:	Clean residue from inside of glass	6414 9999	30 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2047061/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Technical Service Bulletin

Required Parts and Tools

Part Number	Part Description	Quantity
D 096 330 A2	 Window Seal Set	1

Additional Information

All parts and service references provided in this TSB (2047061) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.