

70 Rattle from rear subwoofer grille

70 17 59 2044503/2 March 27, 2017. Supersedes Technical Service Bulletin Group 70 number 16-52 dated June 9, 2016 for reasons listed below.

	Model(s)	Year	VIN Range	Vehicle-Specific Equipment
ſ	A4	2016 - 2017	All	Not Applicable

Condition

REVISION HISTO	RY	
Revision	Date	Purpose
2	-	Revised Warranty (Updated Service Number and Labor Operations)
1	06/09/2016	Initial publication

Customer may report a rattle coming from the rear parcel shelf or rear subwoofer grille when playing music.

Technical Background

The rear parcel shelf speaker grille will rattle when loud music with heavy bass is being played.

Production Solution

Not applicable.

© 2017 Audi of America, Inc.

All rights reserved. Information contrained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Service

Install foam strips (part number 8E0831575A) as shown. Note that there are two different types of speaker grilles, and the foam strips are installed differently on each one:

- Vehicles with Audi sound (PR code 9VD) (Figure 1).
- Vehicles with Bang and Olufsen (PR code 9VS) (Figure 2).




Figure 1. Foam strip installation for vehicles with Audi sound (PR code 9VD).




Figure 2. Foam strip installation for vehicles with <u>Bang and Olufsen (PR code 9VS)</u>.

^{© 2017} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Warranty

Claim Type: • 110 up to 48 Months/50,000 Miles.					
	G10 for CPO Covered Vehicles – Verify Owner.				
	 If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 				
Service Number:	7030				
Damage Code:	0020				
Labor Operations:	Remove, install, and modify 2 trim panels	7030 4999	40 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
	Technical diagnosis at dealer's discretion				
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2044503/2				

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Number Part Description	
8E0831575A	Damping strip (self-adhesive)	2

Additional Information

All parts and service references provided in this TSB (2044503) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2017 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2017 Audi of America, Inc.

Page 4 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.