## Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



DASHBOARD UPPER PANEL WARPING

Bulletin No.: 09-046/17

Last Issued: 12/01/2017

## **BULLETIN NOTES**

This bulletin supersedes the previously issued bulletin(s) listed below: The changes are noted in Red.

Previously issued TSBs:	Date issued:
09-050/16	08/30/16
09-038/14	09/09/14

## APPLICABLE MODEL(S)/VINS

2010-2013 Mazda3 vehicles with VINs between JM1 BL \*\*\*\*\*\* 324925 to 778739 (before January 12, 2013)

## **DESCRIPTION**

This TSB has been superseded to SSPA9.

Page **1** of **1** 

consumer Notice: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing.