

## **Tech Line Summary Article**

**October 2017**BTS 170202 Version 3

## EVAP System Leak from the Filler Neck? *Don't* Replace the Fuel Fill Pipe!

## **AFFECTED VEHICLES**

2017 MDX and 2017 NSX

**EDITOR'S NOTE:** This article replaces the one posted in **June 2017** to extend the article's shelf life. The issue(s) covered are still being addressed.

If there's an EVAP system leak from the filler neck (DTC P0455 [EVAP system large leak detected] or P0456 [EVAP system very small leak detected] is set), **don't** replace the fuel fill pipe! Instead, replace the mis-fuel inhibit device and the main flap unit. Acura parts stock carries replacement parts just for this purpose.

For replacement procedures, refer to the service information.

© 2017 American Honda Motor Co., Inc. - All Rights Reserved