

# **Technical Journal**

TITLE:

# **Hybrid DTC BECM-P0CE100**

_					
	REF NO:	ISSUING DEPARTMENT:	CAR MARKET:		
	TJ 32903.2.0	Technical Service	United States and Canada		
		PARTNER:	ISSUE DATE:	STATUS DATE:	
	3 US 7	7510 Volvo Car USA	2017-10-13	2017-10-19	
	FUNC GROUP:	FUNC DESC:			
	3113	3113 Battery, high voltage		1 of 2	

<sup>&</sup>quot;Right first time in Time"

#### **Attachment**

# **Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	( 'hassis range	Struc Week Range
234	BC	B1BPHEV					2018-2018		0027016-0036478	201717-201739
238	BC	B1BPHEV					2018-2018		0015001-0035789	201717-201739
256	BC	B1BPHEV					2016-2018		0008280-0321806	201526-201739
256	BR	B1FPHEV					2018-2018		0190000-0321806	201717-201739

# **CSC** Customer Symptom Codes

Code	Description			
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication			

# VST Operation Number

VST Operation Number	Description
36002-3	Software control module downloading

### **DTC** Diagnostic Trouble Codes

<b>Control Module</b>	Code	Fault Type		
BECM	P0CE100	Intermittent		

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

# **Technical Journal 32903.2.0**



#### **Text**

#### **DESCRIPTION:**

\*Vehicle profile updated.

The check engine light (CEL) may be illuminated without any other customer symptoms or the code BECM-P0CE100 is read out with VIDA. Please follow the advice under Service.

BECM = Battery Electronic Control Module

#### **SERVICE:**

\* Perform an upgrade of the software according to TJ 31543.

#### **VEHICLE REPORT:**

\* Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3113.

Page 2 of 2 2017-10-19