



Countries: UNITED STATES
Availability: ISIS, NotSIR
Major System: CAB / SLEEPER / HOOD
Current Language: English
Other Languages: NONE
Viewed: 133

Document ID: IK1600240
Revision: 1
Created: 12/19/2017
Last Modified: 12/29/2017
Author: Andrew Boyd

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 3	 0

Title: HX door will not open far enough

Applies To: HX

CHANGE LOG

Dealers: Please refer to the change log text box below for recent changes to this article:

Please refer to the change log text box below for recent changes to this article:

09/23/2015 - Initial Article Release

DESCRIPTION

This document will guide the user through correcting the issue of HX door not opening far enough.

SYMPTOM(s)

Drivers door not opening far enough to gain access to the cab.

SPECIAL TOOL(s) / SOFTWARE

[Tools Resource Center](#)

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes
Passenger side door strap	3514729c1	1	

--	--	--	--

DIAGNOSTIC STEP(s)

 WARNING:	
Enter Warning Here	

CAUTION:	
Enter Caution Here	

REPAIR STEP(s)

Remove drivers side door strap (4104796c1), replace with passenger side strap (3514729c1).

REMOVAL PROCEDURE:

1. Step 1 Remove Drivers side door strap, part number 4104796c1

INSTALLATION PROCEDURE:

1. Step 1 Install Passenger side strap on drivers door, part number 3514729c1

WARRANTY INFORMATION

Warranty Claim Coding:

Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.

Standard Repair Time(s):

Refer to the [SRT Manual](#) for Repair Times

OTHER RESOURCES

[Master Service Information Site](#)

 Hide Details

Feedback Information

Viewed: 132
Helpful: 3
Not Helpful: 0

No Feedback Found

Copyright © 2018 Navistar, Inc.