



Countries: CANADA, UNITED STATES, MEXICO
Availability: ISIS, FleetIS, IsSIR
Major System: ENGINES
Current Language: English
Other Languages: NONE
Viewed: 60

Document ID: IK1201378
Revision: 0
Created: 7/11/2017
Last Modified: 7/17/2017
Author: Amber Chapman

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 0	Not Helpful 0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: A26 - Low Idle Increment Feature no longer supported

Applies To: A26

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

07/14/2017- Initial Article Release

DESCRIPTION

The low idle increment is not available on A26 due to increased emissions constraints.

SYMPTOM(s)

The low idle speed cannot be adjusted though the cruise switches (as available on previous products).

Diagnostic Trouble Code(s) & Dashboard Indicator Light(s):

DTC/Light	Description
N/A	

Customer Observations or Concerns:

Idle adjustment feature is disabled; the driver will not be able to adjust the low idle speed with the cruise switches like on previous product.

This feature does not impact AESC / PTO feature operation.

SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
N/A			

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes
N/A			

DIAGNOSTIC STEP(s)

N/A

REPAIR STEP(s)

No repair available at this time.

WARRANTY INFORMATION

N/A: Informational Only

Warranty Claim Coding:

Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.

OTHER RESOURCES

[Master Service Information Site](#)

Hide Details	Feedback Information
	Viewed: 59 Helpful: 0 Not Helpful: 0
No Feedback Found	