

Subject		Market
<b>Repair Manual Correction - Front Camber Specification</b>		USA
Service Category	Section	
Suspension	Alignment/Handling Diagnoses	
Applicability		
2018 LC and LCh		

**APPLICABLE VEHICLES**

2018	LC500	2018	LC500H
------	-------	------	--------

**CONDITION**

The Repair Manual Specification for Front Camber is incorrect.  
0°42' +/- 0°45' (0.70° +/-0.75°), 0.45' (0.75°) Right-left difference

**RECOMMENDATIONS**

The following are the correct specifications to use:  
-0°42' +/- 0°25' ( -0.70° +/- 0.41°), 0.30' (0.50°) Right-left difference

**LINK REFERENCES**

This Tech Tip does not contain any link references