



Technical Tip

Topic	27-17-04TT – Blind Spot Monitoring Erroneous Signals
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	November 17, 2017

Condition

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN AS TITLED.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Blind Spot Monitoring Erroneous Signals

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf, GTI, eGolf, Sportwagen, Jetta, Passat, Beetle, Beetle Convertible, Tiguan, Tiguan LWB, Atlas, Touareg	2015-2018	All	All	All	All

Technical Background

System may detect a vehicle in a blind spot when there is no vehicle present.

Service

Inspect the entire front and rear fascia for signs of damage or damage repair. Pay close attention around the parking aid and radar sensors when equipped. Improper repairs have been found to cause both un-wanted triggering of the system and phantom vehicles coming from behind (i.e large amounts of adhesive). See figure 1.



Figure 1

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2049390/1	11/17/17	Original publication.

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.