

1 01 21-17



Service Information Bulletin

SUBJECT	DATE
SPN 521050 (CPC3) (GHG17)	January 2017

Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0191	GHG17 Heavy Duty	SPN 521050/FMI 14 - GHG17	This is a new section.

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
 Telephone: 313-592-5000
www.demanddetroit.com

2 SPN 521050/FMI 14 - GHG17

PTConf Error: No Response from MCM for Request

Check as follows:

1. Disconnect DiagnosticLink[®] from the 9-pin connector. **If tool is connected, the fault will not clear.** Turn the ignition OFF; wait until ICUC display goes blank (this ensures all modules have gone offline and may take a few minutes).
2. Turn ignition ON (key ON, engine OFF). Wait one minute and then connect DiagnosticLink. Verify fault is no longer active.