

1 01 22-17



Service Information Bulletin

SUBJECT	DATE
SPN 521058 (CPC3) (GHG17)	January 2017

Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0191	GHG17 Heavy Duty	SPN 521058/FMI 14 - GHG17	This is a new section.

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
Telephone: 313-592-5000
www.demanddetroit.com

2 SPN 521058/FMI 14 - GHG17

PTConf Error: CPC3evo Calibration is Inconsistent

Check as follows:

1. Compare the below CPC3 parameters to OEM settings and adjust as necessary.
 - Grp 227 Single (1) or Dual (2) Wheel on Drive Axle
 - Grp 50 PTO Mode Governor Type
 - Grp 233 Rear Axle Ratio
 - Grp 228 Engine Torque/Power Selection