

1 01 31-17



Service Information Bulletin

SUBJECT	DATE
SPN 521054 (CPC3) (GHG17)	January 2017

Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0191	GHG17 Heavy Duty	SPN 521054/FMI 14 - GHG17	This is a new section.

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
Telephone: 313-592-5000
www.demanddetroit.com

2 SPN 521054/FMI 14 - GHG17

PTConf Error: Data of MCM is Inconsistent

Check as follows:

1. Disconnect DiagnosticLink® from the 9-pin connector (**if tool is connected, fault will not clear**). Turn the ignition OFF and wait until ICUC display goes blank (this ensures all modules have gone offline and may take a few minutes).
2. Turn ignition ON (key ON, engine OFF), wait one minute, and then connect DiagnosticLink. Verify fault is no longer active.
3. Are any other MCM fault codes present?
 - a. Yes; repair those first.
 - b. No; Go to step 4.
4. If fault is active after above steps, reprogram MCM to latest settings.