

<small>Subject</small> Battery Disconnect Precaution		<small>Market</small> USA
<small>Service Category</small> Engine/Hybrid System	<small>Section</small> Engine Control	
<small>Applicability</small> 2018 C-HR		

APPLICABLE VEHICLES

2018

C-HR

CONDITION

If the battery is disconnected incorrectly, the vehicle may exhibit a MIL "ON" condition when restarted.

RECOMMENDATIONS

After turning the ignition switch off, wait a minimum of 90 seconds before disconnecting the negative battery terminal.

LINK REFERENCES

This Tech Tip does not contain any link references