



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-261

Date: October, 2017

INFORMATION

Subject: Engine Overheat When Driving Aggressively with Accessory Grille and Outboard Cooler Installed

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016	2018			All	All

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPOs)	Equipped with Accessory Grille (RPO RZ9 or RZB) and Aux Engine Cooler (RPO V18)
Condition	Some customers may comment on the vehicle overheating when driving aggressively with accessory grille installed in addition to outboard cooler installed.
Cause	This may be due to outboard aero blockers restricting airflow to the outboard coolers, causing the vehicle to overheat.
Correction	If the vehicle is equipped with (RPO V18) outboard coolers and an accessory grille, the grille blockers should not be installed. If installed, they should be removed.

Version	2
Modified	October 16, 2017 – Added the 2017 and 2018 Model Years.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**