Subject: Engineering Information - Rattle Noise from the Drive Support Assembly

This PI has been revised to end the need for information from the field. Please discard PIE0410A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2016	2017			All	All

If you encounter a vehicle with the above condition, refer to bulletin 17–NA-311 for further diagnosis.